



HDI-10

Portable Indicator

www.ctaplus.com

FEATURE

The product shows signal of potentiometer and micro voltage output sense, which used strain gauge, into digital display and analogue output as portable indicator.

- Measuring DATA storage (Max 500)
- Peak hold
- Auto zero
- HI, LO comparison lamp display

SPECIFICATION

Usage voltage	DC 9V battery
Current consumption	15mA
Input signal	Load cell: 1.0 ~ 3.0 mV/V Potentiometer: 100 ~ 10kΩ
Load display	4 1/2 digit LCD
Display range	+19999
Display speed	About 10 times/sec
Decima point	Random setting available
A/D sampling speed	100 times/sec
A/D resolving power	16bit
Zero adjustment range	100% F.S (Auto zero)
Data storage	Measuring data storage (Max 500)
Serial data out	RS232C Serial interface



DIMENSION

